UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO.

7,854,709 B2

APPLICATION NO.

10/596,405

ISSUE DATE

December 21, 2010

INVENTOR(S)

Josef Neff

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. No.	Line(s)	<u>Edits</u>
7	23	Replace "(iii) a drive shaft located the housing" with(iii) a drive shaft located in the housing

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Janet Sleath
SPECKMAN LAW GROUP PLLC
2014B East Union Street
Seattle, WA 98122

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application from to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P O Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P O Box 1450, Alexandria, VA 22313-1450.